

District Office

845 S. Lake St. - P.O. Box 326
Hustisford, WI 53034
(920) 349-8109

Jr./Sr. High School

845 S. Lake St. - P.O. Box 326
Hustisford, WI 53034
(920) 349-3261

John Hustis Elementary

600 S. Hustis. St - P.O. Box 326
Hustisford, WI 53034
(920) 349-3228

Todd Bugnacki

Interim Superintendent

Clint Bushey

Principal

Peter Moe

Principal

Corey Manlick

Director of Financial Services

Alex Pishler

Director of Special Education/Psychologist

Glen Falkenthal

Athletic Director

Buildings and Grounds Committee

Notice is here given that the **Buildings and Grounds Committee** of the Hustisford School District Board of Education will meet on Wednesday, September 3, 2025, at 4:00 p.m. in the Conference Room at Hustisford High School, 845 South Lake Street, Hustisford, WI 53034.

A quorum of the School Board may be present at this committee meeting; however, no official School Board action will be taken at this committee meeting.

School board members on this committee include Kevin Muche, Chair, and Scott Firari, Board Member

Meeting called to order

AGENDA:

1. Building and Grounds Update
 - a. No action required
2. Ice Machine update - the ice machine, primarily used for athletics failed. \$3178 to purchase a new machine. The Booster Club will be covering roughly half the cost and the district will pick up the other half. The machine has been ordered,
 - a. No action required
3. Jr./Sr. High School Rooms 110 and 301 update - AC will not be repaired at a cost of \$1885, as it is not necessary after further investigation. The unit is no longer needed to cool the existing spaces based on the current use of the spaces.
 - a. No action required
4. JHE boilers - The gas bleeder valve needs to be replaced and the touch screen panel on the boiler is no longer operating. Basset will provide a quote on the repairs.
 - a. No action required
5. Filter replacements cost analysis of filters for both buildings - Jr./Sr. High School 4 cycles of replacement cost \$1529, JHE 4 cycles of replacement \$1512.
 - a. No action required
6. Johnson Controls fire alarm system quote discussion - the cost to replace the fire alarm system at the high school is estimated to be around \$22,684.66. (See accompanying documents)
 - a. No action required.
7. Facility Overview - review current facilities master plan and update as necessary. (See accompanying 10 year plan)
 - a. No action required

Next tentative meeting: October 6, 2025 at 4:00 PM

Adjournment

Posted: August 28, 2025

"Notice is hereby given that a majority of the Hustisford School District Board of Education may be present at the above scheduled meeting of the Building and Grounds Committee to gather information about a subject over which they have decision-making responsibility. Should a majority of the Board be present at this meeting, it will constitute a meeting of the Board of Education. The Board will not take any formal action at this meeting."

The Hustisford School District does not discriminate on the basis of age, race, color, sex, national origin, ancestry, religion, creed, pregnancy, marital or parental status, gender, sexual orientation, homelessness status, physical, emotional, or learning disability/handicap, in its curricular, career and technical education programs, co-curricular programs, student services, recreational or other programs and activities, or in admissions or access to programs or activities offered by the school district in its employment practices. The Superintendent of Schools has been designated to handle inquiries regarding non-discrimination issues. He/she can be reached at: Superintendent of Schools, Hustisford School District, 845 South Lake Street, Hustisford, WI 53034 (920-349-8109).